

Tip 1

In circular movement, the feed at the center of the tool (F_2) is smaller than the feed at the cutting edge (F_1)

If the incorrect feed is used while working in a circular movement, one of these problems is likely to occur:


Example: M6 x 1

Tool cutting diameter = 4.8 mm

$F_1 = 238$ (mm/min)

$F_2 = 47$ (mm/min)

- Working too slow - leads to increased machining time (in this example, 5 times longer) and shorter tool life
- Working too fast - a high load on the insert will reduce tool life significantly



Tip 2

Some controllers refer to the feed at the center (F_2) and some to the feed at the cutting edge (F_1)

- In the CNC program, the command "F" defines the tool feed (mm/min, inch/min)
- It is difficult to determine in advance whether the "F" command in the CNC program refers to the tool center or to the cutting edge




- Often, the machine operator is unaware of the feed differences between the tool center and the tool cutting edge



Tip 3


Find out how the machine controller refers to the "F" command

- The machining time calculated by the VARDEX TM Gen is based on the feed at the tool center (F_2)



- If the actual machining time is substantially different than that calculated by the TM Gen, your controller is moving according to the feed on the cutting edge (F_1). Switch to the F_1 value

- The VARDEX TM Gen calculates both F_1 and F_2 , eliminating the need to manually calculate them
- F_1 and F_2 are stored in the data summary page:



For tool selection and cutting data in Thread Turning applications use our **TT Gen**.
 For the best Thread Milling CNC Programming, use **VARDEX TM Gen** software utilities.
 For free copies, go to www.vargus.com
 Now available in 10 languages!!!

